

Howard County Pipe Break Field Data

Location and Contact information			
Date	4-4-11	10202 Maxine Ave	Time 1:00 pm
Crew Leader name	D. Ball		Crew Leader phone #
Address	10202 Maxine Ave		
ADC page		ADC Grid 2940	#30
Base Map #	30-2940	Contract # 194	

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8"
----------------	----