

## Howard County Pipe Break Field Data

	Location and Contact information		
Date	7-2-11	Time	7:00 pm
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	5010 AVOCIA AVE		
ADC page	4936	ADC Grid	A-3
Base Map #	2843	Contract #	12-W

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	8
----------------	---