

Howard County Pipe Break Field Data

Location and Contact information			
Date	5-14-12	Time	10:30 AM
Crew Leader name	David Ball	Crew Leader phone #	410-313-4900
Address	5375 Mad River LA		
ADC page	4934	ADC Grid	K-4
Base Map #	2840	Contract #	205

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----