

Howard County Pipe Break Field Data

Location and Contact information			
Date	5-19-12	Time	7:00 PM
Crew Leader name	Tom Puckett	Crew Leader phone #	
Address	5431 Sylvan Lane		
ADC page	4816	ADC Grid	C-7
Base Map #	24/25 - 3143	Contract #	3820

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite		Copper 1" Cop	

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak	<input checked="" type="checkbox"/>	Valve problem	

Size of Pipe

Size in inches	1"
----------------	----