

## Howard County Pipe Break Field Data

Location and Contact information			
Date	6-6-11	Time	7:00
Crew Leader name	D. Ball	Crew Leader phone #	4900
Address	6240 Foreland Garth		
ADC page	4935	ADC Grid	K-8
Base Map #		Contract #	788

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Hole

### Size of Pipe

Size in inches	6"
----------------	----