

## Howard County Pipe Break Field Data

Location and Contact information			
Date	11-14-2012	Time	8:00am
Crew Leader name	D. Borzell & M. Fisher	Crew Leader phone #	410.313-4900
Address	6405 Anderson Ave		
ADC page	4537	ADC Grid	B-10
Base Map #	24-47	Contract #	2-W

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	8"
----------------	----