

## Howard County Pipe Break Field Data

Location and Contact information			
Date	4/8/12	Time	19:00
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	6611 Devlon Place Elkridge, MD 21075		
ADC page	4936	ADC Grid	D10
Base Map #	2444	Contract #	950

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		hole in pipe	<input checked="" type="checkbox"/>