

Howard County Pipe Break Field Data

Location and Contact information			
Date	5/16/2012	Time	7:30
Crew Leader name	Leo	Crew Leader phone #	.
Address	9494 Pur		
ADC page		ADC Grid	
Base Map #		Contract #	337

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----