

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 032

Location: Governor Warfield Parkway at Twin Rivers Rd.

Inspection Date: April 11, 2018

Inspection Overall Score: 29

Significant Findings:

Poles and paint coating are in good condition. There is some light rust around the anchor bolts tightening nuts on both structures.



Maintenance Issues:

Stop Lines are in fair condition.