

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 050  
**Location:** Centennial Lane at Old Annapolis Rd./Breconshire  
**Inspection Date:** May 1, 2018

**Inspection Overall Score:** 49

### Significant Findings:

Poles are in overall poor condition. Paint coating is in overall poor condition, with considerable areas of rust. SE Corner – pole has vehicle impact damage.



### Maintenance Issues:

Electrical service has damaged conduit.