

Howard County Pipe Break Field Data

	Location and Contact information		
Date	11 27 11	Time	10:00 AM
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	10314 TWINE DEW PL		
ADC page	4935 A-10	ADC Grid	✓
Base Map #	GR10-35-2540	Contract #	556

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	✓	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	✓	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----