Howard County Pipe Break Field Data

	Location and Contact information			
Date 5-1-12		Tir	me	11:00
Crew Leader name	D. Ball	Cr	ew Leader phone #	1/3
Address	10320 Ke	He Dru	m ct	
ADC page	4815	ADC Grid	,	47
Base Map #		Contract #		373

Soil Type

Туре	Check box	Туре	Check box
Clay		Clay/sand	U
Sand		Blue/gray clay	
Silt			

Pipe Type

Туре	Check box	Туре	Check box
Cast iron	V	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite		1	

Type of Break

Туре	Check box	Туре	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	
Dize in inches	("