

Howard County Pipe Break Field Data

Location and Contact information			
Date	11-19-11	Time	11:00 AM
Crew Leader name	George Gibson	Crew Leader phone #	410-313-4900
Address	10349 Sixpence Cir		
ADC page	4935	ADC Grid	A-9
Base Map #	2540	Contract #	556

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----