

Howard County Pipe Break Field Data

	Location and Contact information		
Date	3-1-11	Time	1:30 PM
Crew Leader name	Gibson	Crew Leader phone #	410-313-4900
Address	10958 EIGHT BELLS LA		
ADC page	5053	ADC Grid	35
Base Map #	2639	Contract #	258

Soil Type

Type	Check box	Type	Check box
Clay	<input type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input type="checkbox"/>		<input type="checkbox"/>

Type of Break

Type	Check box	Type	Check box
Circular	<input type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input type="checkbox"/>	Valve problem	<input type="checkbox"/>

Hole in pipe ✓

Size of Pipe

Size in inches	3"
----------------	----