

Howard County Pipe Break Field Data

Location and Contact information			
Date	12-25-12	Time	11:30 Am
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	3501 North Chatham Rd		
ADC page	4815	ADC Grid	G-6
Base Map #	3242	Contract #	11-W

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8"
----------------	----