

## Howard County Pipe Break Field Data

Location and Contact information			
Date	3-4-12	Time	3:30 PM
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	4235 Hermitage Dr.		
ADC page	4815	ADC Grid	B-10
Base Map #	24-3041	Contract #	668

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel	<input checked="" type="checkbox"/>	Plastic polyethylene	
AC/Transite	<input checked="" type="checkbox"/>		

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	8"
----------------	----