

Howard County Pipe Break Field Data

	Location and Contact information		
Date	1-13-12	Time	5:00pm
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	5956 Rosinante Run		
ADC page	4935	ADC Grid	D-7
Base Map #	2641	Contract #	319

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----