

## Howard County Pipe Break Field Data

Location and Contact information			
Date	7/3/12	Time	7:00 AM
Crew Leader Name	CHUCK GARRETT	Crew Leader phone #	
Address	6375 BUSINESS PARKWAY		
ADC page	5054	ADC Grid	G-1
Base Map #	2445	Contract #	1880

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron	<input checked="" type="checkbox"/>	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	8"
----------------	----