

## Howard County Pipe Break Field Data

Location and Contact information			
Date	12-14-12	Time	9:30
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	6411 Sunset light - <u>IN ROAD</u>		
ADC page	4935	ADC Grid	F-9
Base Map #	36-2541	Contract #	486

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	3"
----------------	----