

Howard County Pipe Break Field Data

	Location and Contact information		
Date	4/17/2012	Time	7:50 AM
Crew Leader name	G. Gibson	Crew Leader phone #	U 120
Address	9217 FREDERICK ROAD		
ADC page		ADC Grid	
Base Map #		Contract #	10. W

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	
Fitting leak		Valve problem	

8" 8" long bottom of pipe

Size of Pipe

Size in inches	
----------------	--