

Howard County Pipe Break Field Data

Location and Contact information			
Date	9-20-11	Time	6:00 AM
Crew Leader name	Ball	Crew Leader phone #	U-113
Address	Windharp Way + Browsing Deer		
ADC page	22	ADC Grid	4935 F9
Base Map #		Contract #	486

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8
----------------	---