

## Howard County Pipe Break Field Data

Location and Contact information			
Date	5-9-11	Time	2:30 pm
Crew Leader name	George Gibson	Crew Leader phone #	410-313-4900
Address			
ADC page	4936	ADC Grid	E 10
Base Map #	2444	Contract #	950

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Hole in pipe

### Size of Pipe

Size in inches	6"
----------------	----