

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 005
Location: Broken Land Parkway at Stevens Forest Rd.?
Inspection Date: April 11, 2018

Inspection Overall Score: 21

Significant Findings:

Poles and paint coating in overall good condition.



Maintenance Issues:

N/A

Hazard Identification Beacon:

Eastbound - Newer HIB.



Westbound – Older HIB. One mast-arm bolt is missing and there appears to be space between the mounting plates. The missing bolt should be replaced and the other bolts checked for tightness.

