

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 029


Location: Little Patuxent Parkway at Sterrett/Columbia Mall

Inspection Date: February 27, 2018

Inspection Overall Score: 26

Significant Findings:

Poles and paint coating in overall good condition. Surface rust beginning around the tightening nuts and base plate area.



Maintenance Issues:

Hand holes retaining water.