

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 051  
**Location:** Tamar Rd. at Old Dobbin Rd.  
**Inspection Date:** May 15, 2018

Inspection Overall Score: 44

### Significant Findings:

Poles are in overall fair condition. Paint coating is in overall poor condition, with rust beginning to form in some areas.



### Maintenance Issues:

SE Corner – loose tightening nut.  
Damaged electrical service conduit.