

## Howard County Pipe Break Field Data

Location and Contact information			
Date	12-2-12	Time	3:00 pm
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	5269 Bright Dawn CT		
ADC page	4935	ADC Grid	H-05
Base Map #	2742	Contract #	695 AC

### Soil Type

Type	Check box	Type	Check box
Clay	<input type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input checked="" type="checkbox"/>		<input type="checkbox"/>

### Type of Break

Type	Check box	Type	Check box
Circular	<input type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input checked="" type="checkbox"/>	Valve problem	<input type="checkbox"/>

W.H.C.



### Size of Pipe

Size in inches	6"
----------------	----