## **Howard County Pipe Break Field Data**

|                  | Location and Contact information |              |           |              |
|------------------|----------------------------------|--------------|-----------|--------------|
| Date 3-14-11     |                                  | Time 7:30    | Oam       |              |
| Crew Leader name | D Borrell                        | Crew Leader  | r phone # | 410-313-4800 |
| Address          | 5852 Rc                          | ce Rol.      |           |              |
| ADC page         | 4937                             | ADC Grid G-7 |           |              |
| Base Map #       | 2648                             | Contract #   | 5         | 5-W          |

Soil Type

| Туре | Check box | Туре           | Check box |
|------|-----------|----------------|-----------|
| Clay |           | Clay/sand      |           |
| Sand |           | Blue/gray clay |           |
| Silt |           |                |           |

Pipe Type

| Туре         | Check box | Туре                 | Check box |
|--------------|-----------|----------------------|-----------|
| Cast iron    |           | PCCP/Concrete        | _         |
| Ductile iron | 1000      | Plastic PVC          |           |
| Steel        |           | Plastic polyethylene |           |
| AC/Transite  |           |                      |           |

Type of Break

| 7,750 0.00   |           |                  |           |
|--------------|-----------|------------------|-----------|
| Туре         | Check box | Туре             | Check box |
| Circular     | /         | Damage by others |           |
| Split        |           | Pipe Joint leak  |           |
| Fitting leak |           | Valve problem    |           |

Size of Pipe

| ore or ripe    |     |
|----------------|-----|
| Size in inches | 8.  |
|                | 010 |