

Howard County Pipe Break Field Data

Location and Contact information			
Date	11-19-11	Time	3:00 pm
Crew Leader name	George Gibson	Crew Leader phone #	410-513-4906
Address	DEEP EARTH LA + SNOWDEN RIVER PRWY		
ADC page	4936	ADC Grid	A-8
Base Map #	2543	Contract #	3263

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron	<input checked="" type="checkbox"/>	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8"
----------------	----