

TABLE B-4
Stray Current (Potential) Test Data

| Station Number | Test Number | Test Location | Structure Tested | DC Potential (Volts) |
|-----------------------|--------------------|--------------------------------------|-------------------------|-----------------------------|
| 0+25 | V-1 | Montgomery Rd. @ Old Washington Rd. | Fire Hydrant | 0.58 |
| 0+20 | V-2 | Bonnie View Ln. @ Old Washington Rd. | Fire Hydrant | 0.54 |
| 3+20 | V-3 | Bonnie View Lane @ Hooks Lane | AC Ground | 0.50 |
| 10+00 | V-4 | Bonnie View Lane @ Route 1 | Fire Hydrant | 0.58 |
| 7+67 | V-5 | 6041 Claire Drive | Fire Hydrant | 0.50 |
| 2+57 | V-6 | 5905 Rustic Lane | Fire Hydrant | 0.43 |
| 2+10 | V-7 | 5706 Leaf Lane | Fire Hydrant | 0.49 |
| 0+25 | V-8 | Old Washington Road @ Main Street | AC Ground | 0.57 |
| 5+65 | V-9 | 5915 Old Washington Road | Fire Hydrant | 0.47 |
| 3+00 | V-10 | Brumbaugh Street @ Route 1 | Fire Hydrant | 0.49 |
| 0+25 | V-11 | 5793 Elkridge Heights Road | Fire Hydrant | 0.50 |
| 6+00 | V-12 | 5790 Elkridge Heights Road | Fire Hydrant | 0.53 |