

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-2-04  
 TIME: 2:30 pm  
 TIME OF BREAK: 2:00 pm  
 ENGINEER: G. GIBSON

**LOCATION:**  
 GPS LOCATION: 6634 Dovecote Lane

GPS: 553W

**PHOTO BEFORE REPAIRS:**  
 Number of Pictures:     

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic  
 Pipe Size: 6"  
 Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**



Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures:     

**SKETCH OF SITE**



\* BGC = blue/gray clay