

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-30-06
 TIME: _____
 TIME OF BREAK: 8:00 AM
 ENGINEER: _____

LOCATION:
 GPS LOCATION: 5149 Down West Rd E

GPS: 206

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX	SOIL BOX RESISTIVITIES	pH
(mV)	(Ohm-cm)	(mV)
(mV)	(Ohm-cm)	(mV)
Top of Pipe (12)	Top of Pipe (12)	Top of Pipe (12)
Side of Pipe (3 / 9)	Side of Pipe (3 / 9)	Side of Pipe (3 / 9)
Bottom of Pipe (6)	Bottom of Pipe (6)	Bottom of Pipe (6)
		Actual Soil pH

Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic
 Pipe Size: 6"
 Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:


Form of Break: Circular ___ Longitudinal ___ Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay