

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-12-06  
 TIME: 4:00 pm  
 TIME OF BREAK: 3:00 pm  
 ENGINEER: G. Gibson

**LOCATION:**

GPS LOCATION: HIGH BRIDGE ROAD + N. ROGERS AVE

GPS: 9-W

**PHOTO BEFORE REPAIRS:**

Number of Pictures:     

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: 12"

Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**

Form of Break:  Circular  Longitudinal  Other


**DETAILS:**

7' split

**PHOTO AFTER REPAIRS:**

Number of Pictures:     

**SKETCH OF SITE**



\* BGC = blue/gray clay