

Section 1




Figure 42 – Results of Stray Current Test #1 on Rt 144

Both graphs display readings that are predominantly greater than zero, indicating that there is an underlying steady state voltage gradient present in the area. The overall pattern of the data in both plots carries the typical signature of stray current gradients associated with operation of DC power.