

TABLE B-3
Stray Current (Rosette) Test Data

Direction	Test Location	
	Bonnie View Lane @ Route 1	Brumbaugh Street @ Route 1
0 Degrees	-13.9	9.5
45 Degrees	-10.7	23.2
90 Degrees	-7.4	23.6
135 Degrees	-2.6	35.8
180 Degrees	-12.6	8.3
225 Degrees	-21.7	18.7
270 Degrees	-22.2	10.0
315 Degrees	-37.8	30.3
RESULTANT	50.7	20.5
DIRECTION	291.1 Degrees	268.8 Degrees