

**HOWARD COUNTY DEPARTMENT OF PUBLIC WORKS
CORROSION CONTROL TEST STATION
FIELD DATA SURVEY FORM**

Location: 00+03 Date Surveyed: 3/7/2005
Behind 7180 Millbury Ct. Surveyed by: AC/MJ

T/S #: 8WM #1 Contract #: 10-3696
T/S Type: ST Pipe Size: 12"

Was Test Station located? YES/NO No

TEST STATION CONDITION

Test Box : _____
Terminal Board : _____
Wires : _____
Other : _____

SURVEY DATA

Test Wire Size/Description	Color	P/Cu-CuSO ₄ (V)		P/Zn (V)		Anode (mA)
		"On"	"Off"	"On"	"Off"	
1)						
2)						
3)						
4)						
5)						
6)						
7)						

P/Cu-CuSO₄ = Pipe to Copper - Copper Sulfate Reference Cell
P/Zn = Pipe to Zinc Permanent Reference Cell
"On" = Reading with Anode(s) connected
"Off" = Reading with Anode(s) disconnected
I Anode = Current output of anodes

REPAIRS MADE

Test Box: _____
Terminal Board: _____
Wires: _____
Other: _____

Additional Comments/Recommendations: It appears the house construction activity in the vicinity has buried the test station.



Figure 6 – General area of Test Station 8WM1 – Not Found