HOWARD COUNTY DEPARTMENT OF PUBLIC WORKS CORROSION CONTROL TEST STATION FIELD DATA SURVEY FORM

Cap Proj No : W-8203 Contract #: 44-3480 Location : Marriottsville Rd near TRANSCO Gas Line T/S Type : ST T/S Number : 02 Block Number: A01

Date Surveyed : 02/21/97 Surveyed by : N. Powe/D. Stewart **Pipe Type :** Steel Casing Pipe Size : 12" **ADCMap #:** 11 **Tax Map Number :**

TEST STATION CONDITION

Test Box : No Test Box Terminal Board : No Board Wires : Good **Other :** No Concrete pad.

SURVEY DATA

Test Wire		P/Cu-CuS04 (volts)		P/Zn (volts)		
Size/Description	Color	"On"	"Off"	"On"	"Off"	I anode (mA)
#10	Black		623			
#10	Black		618			
P/Cu-CuSO4 = Pipe to Copper Sulphate Reference Cell						
	P/Zn	=	= Pipe to Zinc Permanent Reference Cell			

P/Zn "ON"

"OFF" I anode = Reading with Anode(s) Disconnected

= Current Output of Anodes

IR Drop Calibration

= Reading with Anode(s) Connected

K = Delta I (A)Delta E (mV)

Direction :

REPAIRS MADE

Test Box: N/A Wires: N/A Board: N/A Other: N/A Comments: Located at 88+00.

DACCO SCI, INC. 10260 Old Columbia Road, Columbia, MD 21046 (410)381-9475 http://members.aol.com/gddaccosci/DACCOSCI.htm 02/21/97



Figure D - 3. Test Station No. 02



Figure D - 4. Close-up of Test Station No. 02

DACCO SCI, INC. 10260 Old Columbia Road, Columbia, MD 21046 (410)381-9475 http://members.aol.com/gddaccosci/DACCOSCI.htm 02/21/97