

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 10-10-05
 TIME: 9:00 AM
 TIME OF BREAK: _____
 ENGINEER: _____

LOCATION: _____
 GPS LOCATION: 8532 Winter Dr Th way

GPS: 745

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX	SOIL BOX RESISTIVITES	pH
(mV)	(Ohm-cm)	(mV)
(mV)	(Ohm-cm)	(mV)
Top of Pipe (12)	Top of Pipe (12)	Top of Pipe (12)
Side of Pipe (3 / 9)	Side of Pipe (3 / 9)	Side of Pipe (3 / 9)
Bottom of Pipe (6)	Bottom of Pipe (6)	Bottom of Pipe (6)
		Actual Soil pH

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic

Pipe Size: 12"

Repair Method: Clamp Weld Cut Other

DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE

