

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 004

Location: Broken Land Parkway at Snowden River Parkway/Patuxent Woods

Inspection Date: April 11, 2018

Inspection Overall Score: 51

Significant Findings:

Poles and paint coating are in overall poor condition with considerable rusting of the poles and mast arms.



Maintenance Issues:

N/A