

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 011
Location: Twin Rivers Rd. at Cross Fox La.
Inspection Date: May 1, 2018

Inspection Overall Score: 56

Significant Findings:

Paint coating is in poor condition with considerable rusting of the poles and mast arms.



Maintenance Issues:

Crosswalks and stop lines are in fair condition.