

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 013
Location: Dobbin Rd. at Oakland Mills Rd.
Inspection Date: May 1, 2018

Inspection Overall Score: 52

Significant Findings:

Poles in overall fair condition, with moderate rusting and deterioration around the base plate area, anchor bolts, and tightening nuts. Recommend media blasting, prime, and re-paint.



Maintenance Issues:

Cabinet door does not shut properly.