

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 021

Location: Little Patuxent Parkway at Gov. Warfield Pkwy. & Banneker Rd.

Inspection Date: April 11, 2018

Inspection Overall Score: 56

Significant Findings:

Poles in overall fair condition. Both north and south median structures have rusting and deterioration around the base plate area, anchor bolts, and tightening nuts. Structural evaluation was completed, and media blasting, prime, and re-paint was recommended.



Maintenance Issues:

N/A