

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 039  
**Location:** Harpers Farm Rd. at Beaverkill Rd.  
**Inspection Date:** April 12, 2018

**Inspection Overall Score:** 18

### Significant Findings:

Poles are in overall good condition. Paint coating is in good condition with a few small areas of coating failure and surface rust forming. Recommend clean, prime, and re-paint.



### Maintenance Issues:

N/A