

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 040

Location: Rogers Ave. at Town and Country Blvd.

Inspection Date: June 6, 2018

Inspection Overall Score: 79

Significant Findings:

Cast iron base plates. Poles are in overall fair condition with significant paint coating failure, and light rust around the base plate area. Span wires have significant rusting



Maintenance Issues:

SE, SW, and NW Corners – loose tightening nuts.

NE Corner – base plate is buried.

