

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 043
Location: Oakland Mills Rd. at Oak Hall Rd.
Inspection Date: May 2, 2018

Inspection Overall Score: 26

Significant Findings:

Poles and paint coating in good condition. Surface rust beginning around the anchor bolts and tightening nuts.



Maintenance Issues:

Stop Lines in fair condition.