

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 044
Location: Dobbin Rd. at McGaw Rd.
Inspection Date: May 2, 2018

Inspection Overall Score: 24

Significant Findings:

Poles and paint coating in overall good condition. Three older poles, and one newer pole on the NW corner.



Maintenance Issues:

SE Corner – loose tightening nuts.