

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 045
Location: Snowden River Parkway at Minstrel Way
Inspection Date: May 2, 2018

Inspection Overall Score: 31

Significant Findings:

Poles in overall fair condition. Paint coating is in fair condition with some areas of coating failure and rust beginning to form.



Maintenance Issues:

West Median – loose tightening nuts. Overgrowth needs to be trimmed away from structure.