

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 053  
**Location:** Frederick Rd. at Plumtree Rd.  
**Inspection Date:** June 6, 2018

**Inspection Overall Score:** 51

### Significant Findings:

Poles are in overall fair condition. SE structure has rusting and deterioration around the base plate area. Paint coating on this structure is in poor condition with considerable rusting. Base plate area should be media blasted, prime, and re-painted.



### Maintenance Issues:

SE Corner – loose tightening nuts. Street name sign possibly rubbing against span wire.



Hazard Identification Beacon:

Older HIB. Paint coating is in fair condition with considerable peeling and some surface rusting. Moderate rusting was found around the base plate weld area. The area should be cleaned, primed, and painted to prevent any further deterioration.

