

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 059
Location: Snowden River Parkway at Snowden Square
Inspection Date: May 2, 2018

Inspection Overall Score: 18

Significant Findings:

Poles are in overall good condition. Paint coating is in overall good condition.



Maintenance Issues:

NE Median – loose tightening nuts.