

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 062
Location: Snowden River Parkway at Tamar Dr.
Inspection Date: April 12, 2018

Inspection Overall Score: 26

Significant Findings:

Poles in overall good condition. East Median Pole has vehicle impact damage. Paint coating is in fair condition, with some areas of coating failure and rust beginning to form.



Maintenance Issues:

West Leg Median – loose tightening nuts.
SW Corner – loose ped pole.
Crosswalks and Stop Lines in fair condition.