

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 070  
**Location:** Montgomery Rd. at Marshalee Rd.  
**Inspection Date:** May 15, 2018

**Inspection Overall Score:** 29

### Significant Findings:

Poles and paint coating in overall good condition. Some light surface rust beginning around the anchor bolts and tightening nuts.



### Maintenance Issues:

NW Corner – loose tightening nuts.  
Several hand holes are holding water.

